

Slide Hammer for Spotter

Use with most spot welders to hammer out dents. Connect the slide hammer to the welder (which is used to hold and weld the copper triangle electrode to the panel) the slide hammer is then used to pull out the damage.



Additional Information

- Triangle plate welds to the panel for quick dent removal.
- Rotate plate to new point when worn.
- Complete with 3pt electrode holder.
- Replacement panel pull triangles available separately, please see part No. 91299.
- To be used with earth fitting and cable, please see Part No. 91247.

<http://powertec.co.uk/product/91951>

